



1 !
DEF FN

2 @
FN

3 #
LINE

4 \$
OPEN

5 %
CLOSE

6 &
MOVE

7 ^
ERASE

8 (
POINT

9)
CAT

0 -
FORMAT

-

/

EDIT

Q <=
ASN PLOT

W <>
ACS DRAW

E >=
ATN REM

R <
INT RUN VERIFY

T >
RND RAND MERGE

Y AND
STR\$ RETURN

U OR
CHR\$ IF

I AT
CODE INPUT IN

O ;
PEEK POKE OUT

P ”
TAB PRINT

+

CAPS LOCK

A STOP
READ NEW

S NOT
RESTORE SAVE

D STEP
DATA DIM

F TO
SGN FOR

G THEN
ABS GOTO

H ↑
SOR GOSUB CIRCLE

J -
VAL LOAD VAL\$

K +
LEN LIST SCREENS

L =
USR LET ATTR

;

”

GRAPHICS

CAPS SHIFT

Z :
LN COPY BEEP

X £
EXP CLEAR INK

C ?
LPRINT CONT PAPER

V /
LLIST CLS FLASH

B *
BIN BORDER BRIGHT

N ,
INKEY\$ NEXT OVER

M .
PI PAUSE INVERSE

,

.

:

EXTENDED

SYMBOL SHIFT



DELETE



SYMBOL SHIFT



BREAK